



Columbia County

BUILDING DEPARTMENT

Inspection Affidavit

Permit Number: 31382

I Charles Timmons, licensed as a(n) Contractor* /Engineer/Architect,
(please print name and circle I (c) type) FS 468 Building Inspector*

License #: 5950 On or about 9/5/13,
did personally inspect the (Date & time)

☐ Metal attachment per manufacturer's instructions ☐ Nailing of purlin per metal manufacturer's instructions

☒ Roof deck attachment ☒ Secondary water barrier ☐ Roof to wall connection

work at 1575 Frontier Dr Lake City, FL 32055
(Job Site Address)

Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)

Signature

Charles Timmons



OK
7C.
9-18-13

STATE OF FLORIDA

COUNTY OF COLUMBIA

Sworn to and subscribed before me this 15th day of SEPTEMBER, 2013

By Regina G. Timmons, Notary Public, State of Florida

Personally known ☒ or

Produced Identification _____ Type of identification produced. _____

(Print, type, or stamp)
REGINA G. TIMMONS
MY COMMISSION # EE 107715
EXPIRES October 20, 2015
Bonded Thru Budget Notary Services

* Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.

* Photographs must clearly show all work and have the permit number indicated on the roof.

* Affidavit and Photographs must be provided when final inspection is requested.

* Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.