

## Columbia County, FL. Building & Zoning New Residential Construction Permit #000039873 Issued June 03, 2020



OWNER: EXODUS 4 LLC PHONE: 3867528653 ADDRESS: 1000 SW MANDIBA DR LAKE CITY, FL 32024

PARCEL: 18-5S-17-09280-169 ZONING: AGRICULTURE - 3 PRRD FLOOD ZONE: X Coords: 30.05,-82.65

SUBDIVISION: OAKS OF LAKE CITY PHASE 2 LOT: 69 BLK: PHASE: UNIT: ACRES: 1.02

CONTRACTOR ADDRESS: PHONE: 867-4994

465 NW ORANGE ST.

NAME: BRYAN ZECHER LAKE CITY, FL 32055 LICENSE: CBC054575 -

**BUSINESS:** BRYAN ZECHER CONSTRUCTION INC

## PROJECT DETAILS

THIS IS THE CONSTRUCTION OF A:	Single Family Dwelling
HEATED AREA (SQFT):	2061
TOTAL AREA (SQFT):	2887
, ,	2007
STORIES:	1
BUILDING HEIGHT:	20
BUILDING CODE CONSTRUCTION TYPE:	V
BUILDING CODE ELEMENT:	В
BUILDING CODE OCCUPANCY TYPES:	Residential
OCCUPANCY USE TITLE:	single family
SETBACKS FRONT:	30
SETBACK SIDE 1:	25
SETBACK SIDE 2:	25
SETBACKS REAR:	25
SEPTIC#:	20-0187
BUILDING CODE EDITION:	Florida Building Code 2017 6th Edition & 2014 National Electrical Code
ELEVATION REGULATION	Subdivision Plat
FINISHED FLOOR REQUIREMENT:	80'
REQUIREMENT NEEDED:	By Nailing Inspection
DOCUMENT NEEDED IS:	a Surveyor letter giving the Finished Floor Elevation
IN FLOODWAY:	N

**Notice:** in addition to the requirements of this permit, there may be additional restrictions applicable to this property that may be found in the public records of this county. The issuance of this permit does not waive compliance by permittee with deed restrictions. **Notice:** all other applicable state or federal permits shall be obtained before commencement of this permitted development.

"WARNING TO OWNER: YOUR FAILURE TO RECORD A NOTICE OF COMMENCEMENT MAY RESULT IN YOUR PAYING TWICE FOR IMPROVEMENTS TO YOUR PROPERTY. IF YOU INTEND TO OBTAIN FINANCING, CONSULT WITH YOUR LENDER OR AN ATTORNEY BEFORE RECORDING YOUR NOTICE OF COMMENCEMENT."

Every permit issued shall become invalid unless the work authorized by such permit is commenced within 180 days after its issuance, or if the work authorized by such permit is suspended or abandoned for a period of 180 days after the time the work is commenced. A valid permit receives an approved inspection every 180 days. Work shall be considered not suspended, abandoned or invalid when the permit has received an approved inspection within 180 days of the previous inspection.