

37

Howard Septic Tank Service Inc

PO Box 180

Branford, FI 32008

386-935-1518

Septic System Inspection

17629 US 27
Ft White FL 32038

With proper maintenance the system, can be expected to function correctly and is unlikely to create an unsanitary condition.

The statement does not constitute an assurance by the authority that the system will continue to function, only that it could, based on the knowledge of the authorized and site conditions.

John Kernal

AUTHORIZED INSPECTOR

10/15/21

DATE

1350 gallon tank